

G100

KINDERGLIJBAAN

TOBOGGAN ENFANT AVEC ÉCHELLE

KINDERRUTSCHBAHN

STAND ALONE JUNIOR SLIDE

TOBOGAN INFANTIL (GRANDE)

SCIVOLO PER BAMBINI

Montagehandleiding Notice de montage Assembling manual Montageanleitung Instrucciones para el montaje Istruzioni di installazione


Leeftijd
Age group
Age / Alter
Edad / Età
4 - 12

EUROPLAY nv
Eegene 9
B-9200 DENDERMONDE
tel. 32.52.22 66 22
fax.32.52.22 67 22
www.europlay.eu

Dat.: 10/06/2021


Rev.: -

Page: 1/5




±90kg

VALHOOGTE / HAUTEUR DE CHUTE /
FALL HEIGHT / FALLHÖHE/
ALTURA DE CAÍDA / ALTEZZA DI CADUTA










VEILIGHEIDSAFSTAND / ESPACE DE CHUTE / SAFETY AREA /
SICHERHEITSAFSTAND / ZONA DE SEGURIDAD / DISTANZA DI SICUREZZA




AFMETINGEN
DIMENSIONS
MASSE
DIMENSIONES
DIMENSIONI
L: 3,3m
Br: 2,2m
H: 6,4m

±22m2


Benodigdheden -- Liste des pièces -- Requisites -- Benötigtes -- Accesorios

1x G100-As-Glijdeel-01		2562 x 1860 x 540	42.63kg	1x G100-As-Ladder-01		2510 x 541 x 200	27.84kg	2x G100-K-Boord-01		907,4 x 685,3 x 19	6.68kg
2x G100-K-Verbinding-01		290 x 80 x 19	0.38kg	1x G100-K-Verbinding-02		467 x 236 x 19	0.69kg	1x G100-K-EuOpzetPI-01		643,1 x 113,3 x 19	0.94kg
				1x G100-K-Verbinding-03		467 x 236 x 19	0.69kg				
2x M8x530				22 x M8				4x M8x40			
8x M8x55				22 x M8				6x M8x100			
2x M10x100				2 x M10				2x 68 x 57 x 44	blue		
				24 x white							


①




②




3




4




5



6



7



8

Bij droog weer moeten alle bouten en schroeven opnieuw aangespannen worden.
Par temps sec il faut resserrer régulièrement toute la visserie.
By dry and warm weather check the tightness of all bolts and screws.
Bei trockenem Wetter müssen alle Schrauben und Bolzen aufs neue angespannt werden.
Para el tiempo seco, se necesita cerrar o ajustar los tornillos y tuercas.
Con tempo asciutto, tutti i bulloni e le viti devono essere avvitati nuovamente.