

S361

Balkjesbrug
Pont souple
Balkenbrücke
Ravine crossing
Puente de vigas
Ponte tibetano

Montagehandleiding Notice de montage Assembling manual Montageanleitung Instrucciones para el montaje Istruzioni di installazione


Leeftijd
Age group
Age / Alter
Edad / Età
4 - 15

EUROPLAY nv
Eegene 9
B-9200 DENDERMONDE
tel. 32.52.22 66 22
fax.32.52.22 67 22
www.europlay.eu


Dat.: 12/10/2016

Rev.: -


Page: 1/5




VALHOOGTE / HAUTEUR DE CHUTE /
FALL HEIGHT / FALLHÖHE/
ALTURA DE CAÍDA / ALTEZZA DI CADUTA



VEILIGHEIDSAFSTAND / ESPACE DE CHUTE / SAFETY AREA /
SICHERHEITSAFSTAND / ZONA DE SEGURIDAD / DISTANZA DI SICUREZZA



Samenvoegingszone avonturenpad
Zone de liaison parcours d'aventures
Verbindungsfeld survival parcours
Linking zone adventure path
Zona de conexión recorrido aventurero
Zona di allineamento percorso d'avventura



AFMETINGEN
DIMENSIONS
MASSE
DIMENSIONES
DIMENSIONI
L: 3,1m
Br: 0,8m
H: 1,4m

23,5m2



S361




Montagehandleiding - Notice de montage
 Assembling manual - Instrucciones para el montaje
 Montageanleitung - Istruzioni di installazione

Dat.: 12/10/2016


Page: 2/5

Benodigdheden - Liste des pièces - Materials - Benötigtes - Accesorios - Requisiti


1x S361-As-Brug-01	2x S361-M-VoetSteun-01	4x S361-H-V-01
		
2980x1232x800 64,5kg	597x146x160 2,9kg	120x1700 14,1kg

12x M10		4x M12	
4x M12			
8x M10x145		4x M12	
4x M10x50		12x (Blue)	
4x M10x150		20x	


01




02




03




04



05



06



07

Bij droog weer moeten alle bouten en schroeven opnieuw aangespannen worden.

Par temps sec il faut resserrer régulièrement toute la visserie.

By dry and warm weather check the tightness of all bolts and screws.

Bei trockenem Wetter müssen alle Schrauben und Bolzen aufs neue angespannt werden.

Para el tiempo seco, se necesita cerrar o ajustar los tornillos y tuercas.

Con tempo asciutto, tutti i bulloni e le viti devono essere avvitati nuovamente.

